

**Fire - Flashback - Whilst oxy/fuel gas cutting and lighting the torch, a flashback to the bottle occurred. This was managed / stopped by the arrestor inline system, on the bottle regulator.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CONCRETE PRODUCTS PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>18/09/2024 13:34:59</b>
<b>SUB ACTIVITY:</b>	<b>HOT WORK</b>	<b>INCIDENT No:</b>	<b>04828</b>