

Fire - Flashback - Whilst oxy/fuel gas cutting and lighting the torch, a flashback to the bottle occurred. This was managed / stopped by the arrestor inline system, on the bottle regulator.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONCRETE PRODUCTS PLANT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	18/09/2024 13:34:59
SUB ACTIVITY:	HOT WORK	INCIDENT No:	04828