

Fatal 1 - Failure to follow isolation procedures

WHAT HAPPENED

During an inspection, the burner platform revealed a minor fuel leak at the pressure gauge of the kerosene pipe. During gauge replacement, operators were observed working without adhering to isolation procedures.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ASPHALT/COATING PLANT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	30/05/2025 14:14:37
SUB ACTIVITY:	ASPHALT & COATED STONE	INCIDENT No:	04872