

# Fatal 6 - TRANSPORT - Collision with parked vehicle

## WHAT HAPPENED

Whilst travelling down a dual carriageway, service fitter van impacted broken-down refrigeration truck at 49 mph. Service fitter van was in the inside lane and misjudged gap between parked vehicle and traffic in outside lane (to be confirmed by CCTV).

## LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	30/05/2025 14:25:02
SUB ACTIVITY:	DRIVER AWARENESS	INCIDENT No:	04873