

Bitumen spillage during delivery

WHAT HAPPENED

Exposed to substance - Bitumen delivery, Tank 1 100/150 overflowed during the last part of the delivery.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ASPHALT/COATING PLANT	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	10/06/2025 11:20:44
SUB ACTIVITY:	DELIVERING BITUMEN	INCIDENT No:	04915