

DISAB portable vacuum cleaner topples over

WHAT HAPPENED

DISAB Portable Vacuum toppled over at 45 degrees coming to rest against extruder guarding.

Causes

Hazard awareness - The risk of not having unit fixed was not foreseen

Systems - No procedure in place for regular inspection

Equipment - Bolt had come lose securing leg

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	MANUFACTURING - MINERALS	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	02/12/2025 19:36:39
SUB ACTIVITY:	MOBILE PLANT	INCIDENT No:	04953