

BEST PRACTICE

LOCATION:
ACTIVITY:
SUB ACTIVITY:
BEST PRACTICE No:
COUNTRY OF ORIGIN:

Quarry
Production and Processing
Aggregate processing
BP2081

ARTICLE YEAR
COMPANY:
COMPANY LOCATION:
COMPANY TEL:

2021
Aggregate Industries
Westleigh Quarry
0000

TITLE	
Removal of bucket belt issues and confined space working	
ARTICLE	
<p>Fatal 1, 4 and 5</p> <p>Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum.</p> <p>Please click on additional pdf do download entry in guide</p>	
ARTICLE IMAGES	
<p>Click image to enlarge</p>	<p>Click image to enlarge</p>
<p>Wheels used on conveyor</p>	