

BEST PRACTICE

LOCATION: Quarry
ACTIVITY: Production and Processing
SUB ACTIVITY: Aggregate processing
BEST PRACTICE No: BP2081
COUNTRY OF ORIGIN:

ARTICLE YEAR: 2021
COMPANY: Aggregate Industries
COMPANY LOCATION: Westleigh Quarry
COMPANY TEL: 0000

TITLE

Removal of bucket belt issues and confined space working

ARTICLE

Fatal 1, 4 and 5

Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum.

Please click on [additional pdf](#) to download entry in guide

ARTICLE IMAGES

Click image to enlarge

Click image to enlarge



Wheels used on conveyor