



BEST PRACTICE

LOCATION:
ACTIVITY:
SUB ACTIVITY:
BEST PRACTICE No:
COUNTRY OF ORIGIN:

Quarry
Production and Processing
Aggregate processing
BP2081

ARTICLE YEAR
COMPANY:
COMPANY LOCATION:
COMPANY TEL:

2021
Aggregate Industries
Westleigh Quarry
0000

TITLE		
Removal of bucket belt issues and confined space working		
ARTICLE		
<p>Fatal 1, 4 and 5</p> <p>Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum.</p> <p>Please click on additional pdf to download entry in guide</p>		
ARTICLE IMAGES		
Click image to enlarge		Click image to enlarge
Wheels used on conveyer		