

## BEST PRACTICE

LOCATION:  
ACTIVITY:  
SUB ACTIVITY:  
BEST PRACTICE No:  
COUNTRY OF ORIGIN:

Quarry  
Production and Processing  
Aggregate processing  
BP2081

ARTICLE YEAR  
COMPANY:  
COMPANY LOCATION:  
COMPANY TEL:

2021  
Aggregate Industries  
Westleigh Quarry  
0000

TITLE



**Removal of bucket belt issues and confined space working**

ARTICLE

Fatal 1, 4 and 5

Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum.

Please click on [additional pdf](#) to download entry in guide

ARTICLE IMAGES

Click image to enlarge



**Wheels used on conveyer**

Click image to enlarge

