

## BEST PRACTICE

LOCATION:	Asphalt/Coating plant	ARTICLE YEAR	2021
ACTIVITY:	Maintenance & Housekeeping	COMPANY:	FM Conway
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Heathrow Asphalt Plant
BEST PRACTICE No:	BP2088	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

### TITLE

**Asphalt drum hydro blasting**

### ARTICLE

**Entry 21130      Finalist      Fatal 1, 3, 4 and 5**

At FM Conway's asphalt plant at Heathrow, it was necessary to regularly remove the build-up of material sticking to the dryer finger lifters in the RAP drum. These fingers lift the material and drop it in front of the heat screen to allow the product to be heated and mixed correctly. Over time, the RAP drum clogged with old material blocking the finger lifters and cooled material stuck to the drum. This causes the plant to run less efficiently and results in more wear and tear on the components due to the increased weight of this material.

FM Conway developed a new system using pressure jets to achieve this.

Please [click here](#) to find out more or additional pdf.

### ARTICLE IMAGES

Click image to enlarge

**Before**

Click image to enlarge



**After**