

## BEST PRACTICE

LOCATION:	Concrete products plant	ARTICLE YEAR	2022
ACTIVITY:	Maintenance & Housekeeping	COMPANY:	Marshalls Plc
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Ramsbottom Works
BEST PRACTICE No:	BP2162	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

### TITLE

**Concrete Block Plant Board Exchange – minimising manual handling and falls from height**

### ARTICLE

#### Topic 3 - Safer handling of materials - Highly Commended

Periodically (5-7yrs) there is a requirement to exchange the boards that are used during the manufacturing process to transfer the block through the concrete block plant at MLP Ramsbottom.

This is not a unique activity, each of our concrete block plants throughout our Group share the same challenge.

Historically, this activity was very labour intensive and required the individuals carrying out the task to invoke repetitive manual handling processes, with the potential to be struck by a moving or falling object, which we identify as No 5 of the MPA Fatal Six (struck by moving or falling objects).

The boards being handled are approximately 30kg in weight and 900mm x 600mm in size. 300 of these boards require exchanging for new ones each period.

Contact with moving objects/falling objects currently represents 22% of workplace injuries at Marshalls. This activity is carried out infrequently but carries out a high potential severity of injury.

Please see **additional pdf below** to see what Marshalls did and the benefits

### ARTICLE IMAGES

