

BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Access & Egress & Working at Height	COMPANY:	Bardon Aggregates
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Manor Farm Quarry, Gloucestershire
BEST PRACTICE No:	BP417	COMPANY TEL:	01285 810926
COUNTRY OF ORIGIN:	United Kingdom		

TITLE

Handrails and steps for the face screen conveyor

ARTICLE

After an internal audit identified a potential fall from height hazard in clearing the conveyor on the face screen, the site team suggested some solutions. The addition of handrails and access steps was agreed upon as they enclose operatives on the main belt and prevent a fall. It also means that operatives do not need to wait for a telehandler or a man basket, which saves time.

The handrails are effective at this sand and gravel site, but would not be advisable at a rock quarry, due to the different type of material stopped on load and the risks of injury and slips.

ARTICLE IMAGES

