

Tyre blow out on front end loader.

WHAT HAPPENED

FEL front right tyre blowout - operative parked machine up for break by the weighbridge. Just as operative was getting ready to get out the cab, the tyre failed and exploded through the side wall and released a high energy of air pressure.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	13/09/2024 13:36:57
SUB ACTIVITY:	TYRES AND WHEELS	INCIDENT No:	04808