

# Failure to follow procedures for control of isolation keys

## WHAT HAPPENED

During an examination of the vessel's isolation procedure, multiple isolation keys were found in an open container on a desk. These keys were designated for 'long-term' isolation locks due to ongoing maintenance activities; however, the keys were not controlled in accordance with company isolation procedures.

## LEARNING POINTS / ACTIONS TAKEN

---

|               |                           |               |                     |
|---------------|---------------------------|---------------|---------------------|
| LOCATION:     | AGGREGATE DREDGER         | ALERT STATUS: | Normal              |
| ACTIVITY:     | GUARDING AND ISOLATION    | DATE ISSUED:  | 05/06/2025 11:43:00 |
| SUB ACTIVITY: | NO SUB ACTIVITY AVAILABLE | INCIDENT No:  | 04888               |