

BEST PRACTICE

LOCATION:	Readymix or mortar plant	ARTICLE YEAR	2022
ACTIVITY:	Transport & Logistics / Delivery	COMPANY:	CEMEX UK
SUB ACTIVITY:	Delivering Admixtures & Chemicals	COMPANY LOCATION:	Aston
BEST PRACTICE No:	BP2166	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE

Admixture Control System

ARTICLE

Topic 3 - Safer handling of materials - Highly Commended

Due to how busy Aston is, we needed to ensure that the admix fill/usage was simplified as much as possible. Previous systems have made the delivery process very messy with spillage inside and outside of the tanks.

The admix delivery drivers have no visible way of seeing what is in the tank. The normal method of filling up the tanks is to put the delivery pipe in the top of the tank and discharge what has been ordered. If the tank can't take the capacity, then the drivers don't know the tank is full until it overflows into the bund.

ARTICLE IMAGES

