

Ti per dGWHHAetPEEetNDC ei

o TsWTsUULRLP

A ðannt r ðrahu l i e rt dt reavg sv eot s ðni vf l i e
kt avg gaot f kj oyt eot ki vüewi v l ys l i e ni rc
sbi hsvri hcsre eot eä bp. yt ki vüewi v yi f
esnnt f oyt ðrahuTi vf l yocoyt frøt r l i e
t vgi gavg oyt x. 5 bsr ri eavg oyt ksfj sbøyt ðrahuT
oyt ki vüewi v ssvu ðansv yøvet ,bcs naey oyt
kaessv s snt ri d oyt i øri we bsr oyt en,øyi ,b
f ssrp

O at s oyt rt ä avg røgel yny ys,f oyt f ssre
h,set f vsckt avg rt ,t i et f kt bsr oyt i øri w
kaessv l i e nrt eet f Toyenacnrt eeart sv oyt f ssr
rt ,t i et yi vf ,t epmyt v oyt frøt r hi wt s rt ,t i et
oyt yi vf ,t ekj ,avg oyt røgeToyten,øf ssr
snt vt f avf tr nrt eeart i vf yøyov sv oyt eot sb
yøannt r ksfj vt i r yørkethei aavg egvðhi vc
kraavgp

. yt frøt r sbøyt ðrahu ø oyt sv,j nt resv l ys
eysa,f snt ri d oyt ej ed w bsr rt ,t i eavg oyt ki hu
f ssr Foyt ki vüewi v eysa,f vscyi dt sahyt f oyt
ðrahu av,t ee f øt hð f s kj oyt frøt rp

Please ensure that when working at the rear of a tipper:

- The safe system of work is followed
- The tailgate is secure
- The safety chain is used
- The correct PPE is worn, especially head protection (on this occasion it probably saved his life)!
- and that the company's haulier rules are followed. "Tailgates must be fitted with a minimum Hex Nut tailgate operation; ideally an automatic gate is preferred. Articulated trailer gates which operate by either gravity or pressure are acceptable"

Due to the design of this particular trailer a hexagon nut could not be fitted.

Hard Hat

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	27/03/2012
SUB ACTIVITY:	PRODUCT DELIVERY	INCIDENT No:	00330