

# Failure to follow isolation procedures

## WHAT HAPPENED

During a site visit whilst maintenance operations were in progress, it was observed that the company isolation and MIC procedures were not followed

## LEARNING POINTS / ACTIONS TAKEN

LOCATION: ASPHALT/COATING PLANT  
ACTIVITY: GUARDING AND ISOLATION  
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal  
DATE ISSUED: 04/06/2025 15:49:18  
INCIDENT No: 04882