

A concern was raised regarding the condition of a section of ducting (5t) which had been installed as part of the new bag filter project. Potential to fall.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|----------------------|---------------------------------------|----------------------|----------------------------|
| LOCATION: | CEMENT PLANT | ALERT STATUS: | Normal |
| ACTIVITY: | MAINTENANCE & HOUSEKEEPING | DATE ISSUED: | 12/09/2024 13:53:58 |
| SUB ACTIVITY: | CEMENT | INCIDENT No: | 03786 |