A concern was raised regarding the condition of a section of ducting (5t) which had been installed as part of the new bag filter project. Potential to fall.

## WHAT HAPPENED

## **LEARNING POINTS / ACTIONS TAKEN**

LOCATION: ACTIVITY: SUB ACTIVITY: CEMENT PLANT MAINTENANCE & HOUSEKEEPING CEMENT ALERT STATUS: DATE ISSUED: INCIDENT No: Normal 12/09/2024 13:53:58 03786