

A lifting attachment slipped off forks, contacting IP's face

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: LIFTING
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 13/09/2024 12:01:55
INCIDENT No: 03797