

Cement tanker arrived on site and as the driver started to undo the hatch on his vehicle for loading, it was identified that the tanker was still under pressure.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|----------------------|---|----------------------|----------------------------|
| LOCATION: | CEMENT PLANT | ALERT STATUS: | Normal |
| ACTIVITY: | TRANSPORT & LOGISTICS / DELIVERY | DATE ISSUED: | 18/09/2024 13:49:53 |
| SUB ACTIVITY: | DELIVERING CEMENT | INCIDENT No: | 04831 |