



BEST PRACTICE

LOCATION:	Asphalt/Coating plant	ARTICLE YEAR:	2022
ACTIVITY:	Maintenance & Housekeeping	COMPANY:	Northstone Materials
SUB ACTIVITY:	Conveyors	COMPANY LOCATION:	Mountfield Asphalt Plant
BEST PRACTICE No:	BP2184	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE	
Easy access dust tray	
ARTICLE	
<p>Highly Commended</p> <p>Northstone Materials Mountfield Asphalt Coating Plant produces Bitmac and Asphalt from a Benninghoven MBA 3000 mixing plant.</p> <p>Whilst there had been no incidents to date, it was felt that there was potential for back strain or hitting their head on the underside of the plant when clearing out fallen material from the collecting conveyor. An operator suggested that there was an opportunity to prevent an injury before it occurred, and the current system of clearing material was time consuming and required double handling of the material leading to inefficiencies.</p> <p>Please see the additional pdf and video that provides information about the easy access dust tray that was designed to acheive these improvements.</p> 	
ARTICLE IMAGES	