



BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR:	2006
ACTIVITY:	Manual handling and storage	COMPANY:	Bardon Aggregates
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Manor Farm Quarry, Gloucestershire
BEST PRACTICE No:	BP302	COMPANY TEL:	01285 810926
COUNTRY OF ORIGIN:	United Kingdom		

TITLE	
Automated weighbridge cleaning	
ARTICLE	
<p>Cleaning beneath the low-level weighbridge with a hosepipe used to be a difficult and time-consuming task, requiring high levels of manual handling.</p> <p>The quarry manager has now found a more effective method. A two inch galvanised steel pipe has been attached alongside the weighbridge complete with several taps which release a fine spray underneath the bridge.</p> <p>For just £500, the new system has reduced manual handling and the risk of slips, trips and falls. The manufacturers of the weighbridge consider it to be good practice, as it maintains accuracy of the bridge for longer and makes it easier to maintain.</p>	
ARTICLE IMAGES	
<p data-bbox="667 835 895 864">Click image to enlarge</p>  <p data-bbox="603 1173 963 1202">Automated weighbridge cleaning</p>	