BEST PRACTICE

LOCATION: Quarry **ARTICLE YEAR:** 2005

ACTIVITY: Manual handling and storage COMPANY: Huntsmans Quarries

SUB ACTIVITY: N/A COMPANY LOCATION: Huntsmans Quarry, Gloucestershire

BEST PRACTICE No: BP164 **COMPANY TEL:** 01451 850555

TITLE

Blow bar replacement to secondary crusher

ARTICI F

Huntsmans Quarries has designed and implemented an improved method of replacing the blow bars of the secondary crusher. The original method involved manually handling the bars in a restricted space out of the crusher housing onto the adjacent walkway and onto a waiting forklift and pallet.

To minimise the amount of manual handling and reduce the risk of trapped hands and fingers, the plant team constructed a tower mounted gantry so that the bars were lifted from ground level and swung straight into place in the crusher.

ARTICLE IMAGES		