

BEST PRACTICE

LOCATION: **ARTICLE YEAR:** 2008
ACTIVITY: Maintenance & Housekeeping **COMPANY:** Hanson Aggregates
SUB ACTIVITY: N/A **COMPANY LOCATION:** Kings Cross Premix, London
BEST PRACTICE No: BP507 **COMPANY TEL:** n/a

TITLE

Cleaning platform for premix chute

ARTICLE

At Hanson™s Kings Cross premix plant in London, there is a need to clean the underside of the discharge area below chute under the pan mixer.

A lack of access into this chute prevented staff from easily cleaning out the hardened concrete. Using an air chisel meant great discomfort, caused manual handling issues and carried a potential fall risk.

To counter this, a working platform was fitted inside the chute to allow access for an employee to stand and work.

A task that was uncomfortable, claustrophobic and potentially dangerous, can now be undertaken with relative ease.

ARTICLE IMAGES

