

INCIDENT ALERT

LOCATION: Mobile Plant
ACTIVITY: Transport / Delivery
SUB ACTIVITY: Mobile Plant

ALERT STATUS: Normal
DATE ISSUED: 23/01/09
INCIDENT No: 00202

TITLE

Aggregates: Komatsu 350 Dumpers

ACCIDENT / INCIDENT DETAILS

Komatsu 350 ADT Failures:

Komatsu 350 ADT Failures / faults were identified in the South West in September.

Komatsu have been contacted and have attended site to investigate the failures.

An update to this alert will be published with the Komatsu findings.

ACCIDENT / INCIDENT IMAGES



Cracks on the Tipper Body

LEARNING POINTS / ACTIONS TAKEN

Always ensure your pre-start safety checks are completed thoroughly, pay close attention to load and stress points. Always ensure your mobile plant is inspected in accordance with the manufactures recommendations.

LEARNING POINTS / ACTIONS IMAGES