

**Guarding broke up under material spillage, this happened in an area above the stair case.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CEMENT PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>PRODUCTION AND PROCESSING</b>	<b>DATE ISSUED:</b>	<b>13/09/2024 12:19:59</b>
<b>SUB ACTIVITY:</b>	<b>CEMENT PRODUCTION</b>	<b>INCIDENT No:</b>	<b>03801</b>