Guarding broke up under material spillage, this happened in an area above the stair case.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CEMENT PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**PRODUCTION AND PROCESSING**	**DATE ISSUED:**	**13/09/2024 12:19:59**
SUB ACTIVITY:	**CEMENT PRODUCTION**	**INCIDENT No:**	**03801**