

A fork lift truck was lifting a pallet of kerbs onto racks, the attachment detached from the mast and crashed to floor along with the pallet of product.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: STOCKPILING AND STACKING
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 13/09/2024 12:31:44
INCIDENT No: 03803