A fork lift truck was lifting a pallet of kerbs onto racks, the attachment detached from the mast and crashed to floor along with the pallet of product.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CONCRETE PRODUCTS PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**STOCKPILING AND STACKING**	**DATE ISSUED:**	**13/09/2024 12:31:44**
SUB ACTIVITY:	**NO SUB ACTIVITY AVAILABLE**	**INCIDENT No:**	**03803**