

The silt retaining wall collapsed. Silt had been added to the stockpile 1hr prior to the collapse.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	WHARF	ALERT STATUS:	Normal
ACTIVITY:	STOCKPILING AND STACKING	DATE ISSUED:	13/09/2024 12:46:41
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04801