

# Quarry face collapse during drilling operation

## WHAT HAPPENED

A contractor was on-site at the quarry and whilst drilling the first row of holes, the face collapsed with approx. 100 tonnes of material falling to the quarry floor.

Please view incident alert 4841 for more information about what happened and recommended actions.

## LEARNING POINTS / ACTIONS TAKEN

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>QUARRYING AND FACE ACTIVITY</b>	<b>DATE ISSUED:</b>	<b>29/10/2024 12:06:19</b>
<b>SUB ACTIVITY:</b>	<b>NO SUB ACTIVITY AVAILABLE</b>	<b>INCIDENT No:</b>	<b>04842</b>