Contractor drills into electric cable

WHAT HAPPENED

Contractor drilled into a 16-25mm 3 phase cable supplying a 63A distribution board which supplies diesel tank and WDLF fire suppression equipment.

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CEMENT PLANT ALERT STATUS: Normal

ACTIVITY: MAINTENANCE & HOUSEKEEPING DATE ISSUED: 05/06/2025 11:56:34

SUB ACTIVITY: CEMENT, LIME AND SLAG INCIDENT No: 04891