

safetyalert

safe work healthy life

Hanson UK

005.03.11

Business line:	Concrete
Subject:	Driver's thumb severed whilst delivering concrete
Location:	East Sussex
Date:	March 2011

Incident Detail

During a delivery of concrete to a customers construction site, a driver was asked to discharge his load into a skip. This was to allow an excavator to 'manage' the material and allow the delivery point and area of use to be separate. During discharge the excavator bucket moved the skip causing the drivers thumb to be crushed between the chute handle and the skip edge. The drivers' thumb at the knuckle was severed and despite the driver being transferred to a specialist hospital, could not be reattached.



Poor delivery setup showing 360 bucket position

The nip point between skip and chute handle

Learning Points / Actions to Prevent Reoccurrence

- Mobile plant should never be operated in the close proximity of personnel.
- Operatives are reminded of our Zero Harm pledges; specifically 'Stop and ask if we feel at risk' – if in doubt suspend the task and contact the site manager.
- Always ensure a safe distance from the delivery chute and the material receptacle / intended destination.