

BEST PRACTICE

LOCATION:	Concrete products plant	ARTICLE YEAR	2021
ACTIVITY:	Pedestrian and transport safety on-site	COMPANY:	Tarmac
SUB ACTIVITY:	No Sub Activity Available	COMPANY LOCATION:	Newark Aggregates blocks
BEST PRACTICE No:	BP2095	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE

Newark VPMP project

ARTICLE

Entry 21034 Finalist Fatal 1, 2 and 6

Newark Aggregates Block plant had a complex traffic route system, with little control for incoming materials and outgoing product. There were several issues with the system that put both drivers and pedestrians at risk. A major review of the plant layout and traffic management was required. This was developed by a team lead by the new site manager including representatives from manufacturing, operations, employees from across the site and representatives from the drivers.

Please [click here](#) for more information or on additional pdf

ARTICLE IMAGES

Click image to enlarge

Click image to enlarge

