Yellow Paint Highlights Outer Wheel Path

Dumper at Rest

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	19/08/2011
SUB ACTIVITY:	MOBILE PLANT	INCIDENT No:	00304