

Fatal 1 - Operator injured interacting with a trough roller

WHAT HAPPENED


An operator's hand was lacerated when they attempted to remove a piece of aggregate

An operator suffered a laceration to his right hand when attempting to flick and remove a piece of aggregate from a moving trough roller on a feed belt. The site had experienced issues previously with the belt scoring and eventually splitting.

The IP was not wearing gloves and the plant was not isolated.

LEARNING POINTS / ACTIONS TAKEN

- Ensure you apply LOTOTO prior to interacting with any machinery. Never be tempted with "I'll just"....
- Review your risk assessments for conveyor safety and use a schematic as shown below to identify dangerous nip points.



- Please review the HSE guidance on **Belt Conveyor Fatal Nip Hazards - SPC/Tech/SI1/11** by following [this link](#).

LOCATION:

QUARRY

ALERT STATUS:

Normal

ACTIVITY:

PRODUCTION AND PROCESSING

DATE ISSUED:

09/10/2023 18:30:29

SUB ACTIVITY:

AGGREGATE PROCESSING

INCIDENT No:

03670