

**Isolation Breach - Operative had followed LOTOTO and was cleaning in area 1. The operative was able to pass through from one lock-off zone to Area 2. When entering the new zone, the operative activated a sensor which started the plant (Precast )**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

|                      |                                       |                      |                            |
|----------------------|---------------------------------------|----------------------|----------------------------|
| <b>LOCATION:</b>     | <b>CONCRETE PRODUCTS PLANT</b>        | <b>ALERT STATUS:</b> | <b>Normal</b>              |
| <b>ACTIVITY:</b>     | <b>MAINTENANCE &amp; HOUSEKEEPING</b> | <b>DATE ISSUED:</b>  | <b>03/09/2024 17:11:44</b> |
| <b>SUB ACTIVITY:</b> | <b>CONVEYORS</b>                      | <b>INCIDENT No:</b>  | <b>03743</b>               |