

**Isolation Breach - Operative had followed LOTOTO and was cleaning in area 1. The operative was able to pass through from one lock-off zone to Area 2. When entering the new zone, the operative activated a sensor which started the plant (Precast )**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

**LOCATION:** CONCRETE PRODUCTS PLANT  
**ACTIVITY:** MAINTENANCE & HOUSEKEEPING  
**SUB ACTIVITY:** CONVEYORS

**ALERT STATUS:** Normal  
**DATE ISSUED:** 03/09/2024 17:11:44  
**INCIDENT No:** 03743