

Isolation Breach - Plant operator attempting to clear stone blockage from jaw crusher climbed over stuck rock with equipment still on with the engine running. The conveyor observed to be running, with the crusher jaws off.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	High Potential
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	03/09/2024 17:38:36
SUB ACTIVITY:	AGGREGATE PROCESSING	INCIDENT No:	03747