Isolation Breach - contractor working on unblocking a screw feeder, completed the isolation, but no company representative padlock was attached to the isolation point.

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

LOCATION: CEMENT PLANT ALERT STATUS: Normal

ACTIVITY: MAINTENANCE & HOUSEKEEPING DATE ISSUED: 03/09/2024 17:48:19

SUB ACTIVITY: CEMENT INCIDENT No: 03749