

Whilst preparing products for loading onto lorries in at a precast concrete stocking yard, a stack of pallets collapsed. It was lucky that no one was in the area when the incident occurred as they could have been seriously injured.

## WHAT HAPPENED

## LEARNING POINTS / ACTIONS TAKEN

---

LOCATION: CONCRETE PRODUCTS PLANT  
ACTIVITY: LOADING AND UNLOADING  
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal  
DATE ISSUED: 11/09/2024 16:44:36  
INCIDENT No: 03759