

Customer interacted with the telehandler forks, which led to trapping their finger and serious injury.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	READYMIX OR MORTAR PLANT	ALERT STATUS:	Normal
ACTIVITY:	PEDESTRIAN AND TRANSPORT SAFETY ON-SITE	DATE ISSUED:	11/09/2024 18:41:24
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03765