

Front end loader reversed into a 4x4 in the stockyard.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PEDESTRIAN AND TRANSPORT SAFETY ON-SITE	DATE ISSUED:	11/09/2024 18:50:25
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03766