

Hit by vehicle - operator walking in shed and came into contact with moving fork lift truck – he was knocked to the ground. FLT immediately came to a stop.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: PEDESTRIAN AND TRANSPORT SAFETY ON-SITE
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 11/09/2024 19:01:48
INCIDENT No: 03769