

Hit by vehicle - operator walking in shed and came into contact with moving fork lift truck – he was knocked to the ground. FLT immediately came to a stop.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONCRETE PRODUCTS PLANT	ALERT STATUS:	Normal
ACTIVITY:	PEDESTRIAN AND TRANSPORT SAFETY ON-SITE	DATE ISSUED:	11/09/2024 19:01:48
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03769