

**Hit by vehicle - operator walking in shed and came into contact with moving fork lift truck – he was knocked to the ground. FLT immediately came to a stop.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

**LOCATION:** CONCRETE PRODUCTS PLANT  
**ACTIVITY:** PEDESTRIAN AND TRANSPORT SAFETY ON-SITE  
**SUB ACTIVITY:** NO SUB ACTIVITY AVAILABLE

**ALERT STATUS:** Normal  
**DATE ISSUED:** 11/09/2024 19:01:48  
**INCIDENT No:** 03769