

Gap in ladder on stack allowed fall arrest system to come loose.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CEMENT PLANT	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	11/09/2024 19:07:17
SUB ACTIVITY:	N/A	INCIDENT No:	03770