

Driver was observed to be standing on vehicle chute whilst undertaking cleaning work on a truckmixer

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: READYMIX OR MORTAR PLANT
ACTIVITY: ACCESS & EGRESS & WORKING AT HEIGHT
SUB ACTIVITY: N/A

ALERT STATUS: Normal
DATE ISSUED: 11/09/2024 19:33:20
INCIDENT No: 03776